

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number RSD0007246846	2. Page 1 of 1	3. Emergency Response Phone 1800/468-3710	4. Manifest Tracking Number 008037708 FLE
5. Generator's Name and Mailing Address Clean Harbors Env Services Inc 2545 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME		
6. Transporter 1 Company Name Waste Inc			U.S. EPA ID Number NE0981723513		
7. Transporter 2 Company Name			U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 68145 Facility's Phone: (308) 235-4017			U.S. EPA ID Number NE0981723513		
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity
			No.	Type	12. Unit Wt./Vol.
	X	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), B, PG III	1	DR	15
		2.			
		3.			
		4.			
13. Waste Codes					
					D004 D005 D007
					D008 D039 D040
14. Special Handling Instructions and Additional Information 1. CH831505X08 ERG#171 TRUCK# CHRT#					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Offor's Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____					
TRANSPORTER INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____				
	17. Transporter Acknowledgment of Receipt of Materials				
	Transporter 1 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____				
	Transporter 2 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____				
DESIGNATED FACILITY	18. Discrepancy				
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection				
	18b. Alternate Facility (or Generator) _____ Manifest Reference Number: _____ U.S. EPA ID Number _____				
	Facility's Phone: _____				
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____				
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					
1. H040		2.		3.	
				4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a					
Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____					

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037708 FLE		
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400					Generator's Site Address (if different than mailing address) SAME		
6. Transporter 1 Company Name Neier Inc					U.S. EPA ID Number IND984868406		
7. Transporter 2 Company Name					U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 69145 (308) 235-4012					U.S. EPA ID Number NED981723513		
9a. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))							
9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III		No. Type 1 CM		EST 12	Y	D004	D005
						D007	
						D008	D039
						D040	
14. Special Handling Instructions and Additional Information 1. CH831506X0B ERG#171 TR TLH CHRT 25875							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Officer's Printed/Typed Name Jim Tyson				Signature <i>Jim Tyson</i>		Month Day Year 9 7 15	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name Jimmy Thomas				Signature <i>Jimmy Thomas</i>		Month Day Year 12 7 15	
Transporter 2 Printed/Typed Name				Signature		Month Day Year	
18. Discrepancy							
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
Manifest Reference Number:							
18b. Alternate Facility (or Generator) U.S. EPA ID Number							
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator) Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H040		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Thomas Clark				Signature <i>Thomas Clark</i>		Month Day Year 02 09 15	

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KS0007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037708 FLE								
5. Generator's Name and Mailing Address Green Harbor Env Serv LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME										
6. Transporter 1 Company Name Neier Inc			U.S. EPA ID Number IND984868406										
7. Transporter 2 Company Name			U.S. EPA ID Number										
8. Designated Facility Name and Site Address Clean Harbors Env Services Inc 2247 South Highway 71 Kimball, NE 68145 Facility's Phone: (308) 235-4012			U.S. EPA ID Number NE0981729513										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes						
			No.	Type									
	X	1. NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, LEAD), 9, PG III	1	CM	EST 12	Y	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:33%;">D004</td> <td style="width:33%;">D005</td> <td style="width:33%;">D007</td> </tr> <tr> <td>D008</td> <td>D039</td> <td>D040</td> </tr> </table>	D004	D005	D007	D008	D039	D040
	D004	D005	D007										
	D008	D039	D040										
	2.												
	3.												
	4.												
14. Special Handling Instructions and Additional Information 1. CH93150EX05 ERG#171 TRUCK# CHRT# CHRT 258751													
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.													
Generator's/Officer's Printed/Typed Name Jim Tison Signature <i>[Signature]</i> Month Day Year 12 7 15													
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____												
	17. Transporter Acknowledgment of Receipt of Materials												
	Transporter 1 Printed/Typed Name Jimmy Thomas Signature <i>[Signature]</i> Month Day Year 12 7 15												
	Transporter 2 Printed/Typed Name Signature Month Day Year												
DESIGNATED FACILITY	18. Discrepancy												
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection												
	18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number												
	Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year												
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)													
1. H040		2.		3.		4.							
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a													
Printed/Typed Name Thomas Clark Signature <i>[Signature]</i> Month Day Year 12 09 15													



2247 South Highway 71
Kimball, NE 69145

TEL 308-235-4012
FAX 308-235-4307
www.cleanharbors.com

DATE: 2/9/2015

MANIFEST: 008037708FLE

Dear Valued Customer:

In accordance with 40 CFR 264.12(b), Clean Harbors Environmental Services, Inc., Kimball Facility, has appropriate state and federal permits to accept, store, and/or treat the waste you shipped to our facility. This letter should be kept on file with your copy of the signed manifest.

Clean Harbors Environmental Services, Inc. makes every effort to ensure that signed copies of manifests are returned to the waste generator as quickly as possible following receipt of your waste at our facility. This allows us to provide you with rapid verification that your waste shipment arrived safely at our waste management facility.

Once your waste has been received, Clean Harbors' personnel will verify that the quantity that has been received matches the quantity that was shipped. We also inspect the material and conduct testing to ensure that it meets the facility's waste acceptance criteria as described in our Waste Analysis Plan, as well as processing requirements. Every effort is made to complete the waste verification as quickly as possible; however, it is possible that the signed copy of the manifest may be returned to you before the waste verification process is completed. If a significant discrepancy, as defined by US EPA regulations (40 CFR 264.72), is discovered during the waste verification process, we will contact you in order to reconcile the discrepancy. Additionally, we will work with you to make any corrections to the waste manifest that are necessary.

Sincerely,

Receiving Department